

On/Off Fan Clutch - Repair Kit Cross Reference



Horton Repair Kits	Legacy Horton Repair Kits	Repair Kits w/ Single Row Bearings
 <p>1S-DP-S</p>	<p>Q995569, 995669, 994353, 994902, 995609</p>	<p>14-256-1, ABP N20 142561, FLT14-256-1, KQ795669, FCQ795669, FCR5669</p>
 <p>1S-DP</p>	<p>Q995568, 995550, 995530, 994348, 995607, 795568, 995568, 995606, 995635</p>	<p>14-256, 14-500, ABP N20 14256, ABP N20 14500, FLT14-256, FLT14-500, KQ795568, FCQ795568, FCR5568, 994985, 994900, 994347</p>
 <p>1S-DP-L</p>	<p>Q995575, 995575, 995567, 995608</p>	

Note: Repair kits with extended fan studs available. Questions? Contact Horton at info@hortonww.com

Two-Speed Fan Clutch - Repair Kit Cross Reference



Horton Repair Kits	Legacy Horton Repair Kits	Repair Kits w/ Single Row Bearings
 <p data-bbox="466 381 594 415">2S-DP-S</p>	<p data-bbox="936 381 1105 415">Q995617-S</p>	<p data-bbox="1357 360 1958 439">24-256-1, ABP N20 242561, FLT24-256-1, KQ795669-2, FCQ795669-2, FCR5669-2</p>
 <p data-bbox="498 581 594 615">2S-DP</p>	<p data-bbox="744 536 1295 656">Q995617, Q995582, 995543, 995547, 995617, 995582, 995559, 995557, 995591</p>	<p data-bbox="1391 636 1929 714">24-256, ABP N20 24256, FLT24-256, KQ795582, FCQ795582, FCR5582, 995509, 995510</p>
 <p data-bbox="472 778 594 812">2S-DP-L</p>	<p data-bbox="936 778 1105 812">Q995617-L</p>	

Note: Repair kits with extended fan studs available. Questions? Contact Horton at info@hortonww.com